

Service Bulletin No: 52-001

Ref No: 219

Modification No: EC-17-0086

ATA Chapter: 52

**DOORS - DOOR ASSEMBLY, FRAME 6
REPLACEMENT WITH SEAT CUSHION STOWAGE AND NEW CONTROL STICK STOWAGE ON THE
RADIO RACK****1. Planning Information****A. Effectivity**

All PC-6 aircraft MSN 624, 630, 633, 639 thru 641, 643, 644, 648, 649, 749, 751, 757, 759 and 761.

B. Concurrent Requirements

None.

C. Reason**(1) Problem**

Adjustment of the Pilot's seating position is achieved with removable cushions. Currently there is no suitable stowage position for the cushions within the cabin when not required.

(2) Cause

There is no convenient stowage point within the cabin for the cushion when not required.

(3) Solution

The old door assembly at frame 6 is removed. A new door with cushion stowage is installed. A new position for control stick stowage is installed on the radio rack.

D. Description

This Service Bulletin gives the data and instructions to do the removal, installation work as follows:

- Get access to the work area
- Remove the old door assembly, frame 6
- Install the control stick stowage on the radio rack
- Install the new door assembly, frame 6
- Install the disturbed systems.

E. Compliance

Optional.

F. Approval

The technical content of this Service Bulletin is approved under the authority of DOA No. EASA. 21J. 357.

PILATUS advises Operators/Owners to check with their designated Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Copyright and Legal Statements

© Pilatus Aircraft Ltd. This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be copied, reproduced or translated to other languages without the prior written consent of Pilatus Aircraft Ltd.

In connection with the use of this document, Pilatus does not provide any express or implied warranties and expressly disclaims any warranty of merchantability or fitness for a particular purpose. This document contains trade secrets, confidential and/or proprietary information of us and technical data subject to export control laws and regulations, including the U.S. Export Administration Regulations (EAR). Disclosure or distribution of this document contrary to the EAR, and other laws and regulations, is strictly forbidden. The above restrictions may apply to data on all pages of this document.

H. Manpower

	Total
Preparation	1.0
Modification	7.5
Close up	1.0
TOTAL MAN-HOURS	9.5

NOTE: Man-hours figures do not include the time required to cure sealants, paints and adhesives.

I. Weight and Balance

(1) Weight Change

+0.621 kg (+1.369 lb.).

(2) Moment Change

+5.374 mkg (+47.564 lb-in).

J. Electrical Load Data

Not changed.

K. Software

Not changed.

L. References

Aircraft Maintenance Manual (AMM): 12-11-28, 20-40-10, 24-00-00, 28-00-00.

Structural Repair Manual (SRM): 51-00-03, 51-00-07.

M. Publications Affected

Illustrated Parts Catalogue (IPC): 25-71-01, 52-51-01.

N. Interchangeability of Parts

Pre and Post-Service Bulletin 52-001 items are not interchangeable.

2. Material Information

A. Material - Price and Availability

Operators that require additional information and/or Service Bulletin Material should contact their authorized Pilatus Service Center, or Pilatus Customer Support on www.pilatus-aircraft.com → contact us.

Operators are requested to advise Pilatus Aircraft Ltd, using the Service Bulletin Evaluation Sheet, of the Manufacturer's Serial Number (MSN) and the flying hours of aircraft which are allocated for this Service Bulletin.