

FOR PLANNING PURPOSES

SERVICE BULLETIN

SERVICE BULLETIN NO: 71-006

REF NO: 159

MODIFICATION NO: 020122

ATA CHAPTER: 71

POWERPLANT - STRIPDOWN/BUILD-UP ELECTRICAL HARNESS - CHANGE THE ROUTING

1. Planning Information

A. Effectivity

All PC-12 and PC-12/45 aircraft from MSN 101 thru MSN 455.

B. Concurrent Requirements

None.

C. Reason

Incorporation of this Service Bulletin (SB) changes the routing of the left loom of the engine electrical harness. The new routing position decreases the risk of chaff damage to the wires in the applicable loom.

D. Description

This SB gives the data and instructions necessary to change the routing of the left loom of the engine electrical harness.

E. Compliance

Recommended.

F. Approval

The technical aspects of this SB are approved by the Federal Office for Civil Aviation (FOCA) of Switzerland.

PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that can affect the embodiment of this SB.

G. Manpower

	Total
Preparation	0.25
Modification	1.0
Close up	0.50
TOTAL MAN-HOURS	1.75

H. Weight and Balance

(1) Weight Change

Not affected.

(2) Moment Change

Not affected.

I. Electrical Load Data

Not changed.

J. Software

Not changed.

K. References

Aircraft Maintenance Manual (AMM), 06-20-00, 71-00-00.

L. Publications Affected

AMM, 71-00-02.

M. Interchangeability of Parts

Not applicable.