

Service Bulletin No: 11-005

Ref No: 287

Modification No: EC-11-0302

ATA Chapter: 11

**PLACARDS AND MARKINGS - EXTERNAL PLACARDS -
REPLACE THE FUEL FILLER PLACARD****1. Planning Information****A. Effectivity**

All PC-12, PC-12/45, PC-12/47 and PC-12/47E Series aircraft MSN 101 thru 888, 1001 thru 1299, 1301 thru 1340.

MSN 1300 and 1341 and up will have this modification incorporated at production.

B. Concurrent Requirements

None.

C. Reason

(1) Problem:

The current fuel filler placard does not display an "Anti-ice Additive Required" statement.

(2) Solution:

Add new placards.

D. Description

This Service Bulletin gives the data and instructions necessary to add new fuel filler placards.

E. Compliance

Recommended.

F. Approval

The technical content of this document is approved under the authority of DOA No. EASA. 21J. 357.

PILATUS advises Operators/Owners to check with their designated Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Copyright

© Pilatus Aircraft Ltd. This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be copied, reproduced or translated to other languages without the prior written consent of Pilatus Aircraft Ltd.

H. Manpower

Task	Manhours
Preparation	0.25
Modification	0.25
TOTAL MAN-HOURS	0.5

I. Weight and Balance:

None.

J. Electrical load Data:

Not changed

K. Software:

Not affected.

L. References:

Aircraft Maintenance Manual (AMM)

12-A-20-31-00-00A-070A-A 12-B-20-31-00-00A-070A-A

12-A-11-00-00-00A-901A-A 12-B-11-00-00-00A-901A-A

M. Publications Affected:

IPC

AFM Temporary Revisions:

- AFM Document Number 01973-001 - TR 48 (incorporated at AFM Revision 16)
- AFM Document Number 02211 - TR 21 (incorporated at AFM Revision 8)
- AFM Document Number 02277 - TR 24 (incorporated at AFM Revision 12).

N. Interchangeability of Parts:

Not interchangeable.

2. Material Information**A. Material - Price and Availability**

Pilatus advise that the standard lead times for the parts may be up to 4 weeks.

If you require more information about this modification, please contact us as follows:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND

General Aviation:
Tel: + 41 41 619 3333
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT
11755 AIRPORT WAY
BROOMFIELD, CO 80021.
UNITED STATES OF AMERICA

Tel: 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (PTY.) LTD,
17 JAMES SCHOFIELD DRIVE,
ADELAIDE AIRPORT SA 5950,
AUSTRALIA

Tel: (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: SupportPC12@pilatus.com.au

B. Warranty

Parts will be supplied free-of-charge for all affected aircraft providing the aircraft is within the two year warranty period and the work will be accomplished by an Authorized Service Center within 12 months from the issue date of this Service Bulletin.