

FOR PLANNING PURPOSES

SERVICE BULLETIN

SERVICE BULLETIN NO: 79-001

REF NO: 016

MODIFICATION NO: 960596

ATA CHAPTER: 79

OIL COOLER SUPPORT BRACKET - REPLACEMENT

1. Planning Information

A. Effectivity

- (1) All aircraft up to and including MSN 160.
- (2) This Service Bulletin will be incorporated prior to delivery on aircraft MSN 161 and subsequent.

B. Reason

Instances of the bracket developing cracks which necessitates the replacement of the bracket by a stronger bracket.

C. Description

Accomplishment of this Service Bulletin consists of completing the following tasks:

- (1) Drain the engine oil.
- (2) Remove the oil cooler.
- (3) Remove the old support bracket.
- (4) Install the new bracket.
- (5) Install the oil cooler.
- (6) Fill the engine oil system and ground run the engine.

D. Compliance

Highly recommended.

E. Approval

The technical aspects of this Service Bulletin have been approved by the Federal Office for Civil Aviation (FOCA) of Switzerland.

NOTE: PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

≡PILATUS≡
PC12
SERVICE BULLETIN

FOR PLANNING PURPOSES

F. Manpower

Task	Man-hours
Preparation	1.0
Modification	2.0
Close-Up	1.0
 TOTAL MAN-HOURS	 4.0

NOTE: Man-hours figures are calculated for unit installed in the aircraft and represent the total time estimated for the task.

G. Material - Cost and Availability

(1) Material

Operators should send orders, for Service Bulletin modification kits, to their Authorized PILATUS PC-12 Service Center

or:

PILATUS AIRCRAFT LTD,
CUSTOMER LIAISON MANAGER,
CH 6371 STANS,
SWITZERLAND.

Tel No: +41 41-6196 233
Fax No: +41 41-6103 351

NOTE: Operators are requested to advise Pilatus Aircraft Ltd. of the Manufacturers Serial Number (MSN) and the flying hours of aircraft which are allocated for this Service Bulletin.

(2) Cost and Availability

H. Tooling

I. Weight and Balance

Not Affected.

J. References

Aircraft Maintenance Manual, Chapter 79-00-00 and 79.20.01.

Structure Repair Manual - General