

Ref. No.	Issue Date	Title	SB No.
1	20/04/1961	Introduction	N/A
2	20/04/1961	Operating Mechanism of Fuel Valve	N/A
3	20/04/1961	O-Rings for Fuel Tank Covers from PORTER Serial No. 342	N/A
4	26/04/1961	Lubrication of Felt Washer in S4 and S6 Bendix Magneton	N/A
5	12/05/1961	Propeller Pitch Control	N/A
6 Rev. A	07/07/1961	Reinforcement of the Bearing of the Horizontal Stabilizer	N/A
7	16/06/1961	Pitch Control Linkage Bearing on Cylinder No. 3	N/A
8 Rev. A	07/07/1961	Increase of Maximum Gross Weight	N/A
9 Rev. A	07/07/1961	Reduction on Never Exceed Speed	N/A
10 Rev. A	01/02/1965	Shock Absorber Strut Attachment Fitting at Station 8.68	N/A
11	19/07/1961	Repair Instruction for Engine Front Cowling	N/A
12 Rev. B	01/01/1969	Fuel Tank Repair	N/A
13	27/07/1961	Tire Pressure of Main Wheels	N/A
14	02/08/1961	Bearing Supports on Ailerons and Flaps	N/A
15	18/08/1961	Door Handle of Rear Door in Cabin	N/A
16	30/01/1962	Actuating Levers of Carburetor Heat	N/A
17	30/01/1962	Replacement of the Bolts in Control Mechanism	N/A
18	30/01/1962	Gust Lock on the Control Stick	N/A
19	30/01/1962	Clear-Vue Panel	N/A
20	31/01/1962	Fuel Booster Pump	N/A
21	11/10/1962	Controls, "Lateral Stability"	N/A
22	18/02/1963	Operating Instructions	N/A
23	07/03/1963	Fuel Tank Vent System	N/A
24	01/01/1964	Rudder Pedal Support	N/A
25	01/01/1964	Aileron Balance Weight	N/A
26	01/01/1964	Horizontal Stabilizer Screw Jack Support on Frame 12, Replacement of Seeger Ring	N/A
27 Rev. A	01/11/1965	Horizontal Stabilizer	N/A
28	09/04/1964	Speed Limits with Skis Installed	N/A
29	09/04/1964	Installation of Additional Primer Line Clamps	N/A
30	09/04/1964	Propeller Check	N/A
31	21/04/1964	Recommended Overhaul Periods for Lycoming Engines	N/A
32 Rev. A	08/02/1965	Increased Gross Weight 44850 LBS (2200 kg)	N/A
33 Rev. A	01/02/1965	Selector Valve for Air Intake Heating	N/A

Ref. No.	Issue Date	Title	SB No.
34	01/01/1965	Battery Installation Below Pilot's Seat	N/A
35	01/06/1965	Lower Part of Shock Absorber Leg of Landing Gear	N/A
36	01/09/1965	Fuel Valve	N/A
37	21/04/1965	Inspection Recommendations Following Overspeed or Overboost of Lycoming Engines	N/A
38	20/04/1965	Casing Reinforcement Reduction Gear on Propeller Ratier Figeac	N/A
39	21/04/1965	Re-Routing of Governor Air Pressure Line in Accordance with UACL Service Bulletin No. 27	N/A
40 Rev. A	01/06/1968	Mounting Plates for Horizontal Stabilizer	N/A
41	01/11/1965	Reinforcement of Rear Part of Fuselage Between Bulkheads No. 12 and No. 13	N/A
42	01/09/1965	Sliding Door on Right-Hand Cabin Side	N/A
43	01/09/1965	Supports for Attaching External Stores on Left and Right-Hand Wings	N/A
44	01/11/1965	Cooling of Lower Part of Engine Bearer Foot on Right-Hand Side	N/A
45	01/09/1965	Propeller Pitch Control	N/A
46	01/09/1965	Brackets for Attaching Floats on Lower Side of Fuselage	N/A
47	01/09/1965	Passenger Seat Storage Behind Bulkhead 6	N/A
48	01/01/1966	Air Inlet Duct in Nose Section	N/A
49	01/11/1965	Lower Rudder Connecting Flange	N/A
50	01/12/1965	Reinforcement at the Outer Bearing of Elevator Assembly	N/A
51	01/12/1965	Engine Support Strut of Astazou II Engine Mounting	N/A
52	01/11/1965	Lycoming Engines Magneto Drop-Off	N/A
53	01/11/1965	Lycoming Engines Cylinder Modification to Prevent Cracks at Plug Locations	N/A
54	01/01/1966	Oil Hose 6543.27 between Engine and Oil Cooler	N/A
55	01/01/1966	Actuation of Fuel Injection Valve	N/A
56	01/01/1966	Engine Mount Ring	N/A
57	01/03/1966	Securing of Aileron and Landing Flap Bearings	N/A
58	01/03/1966	Protection Bellows on Landing Gear Struts	N/A
59	01/10/1966	Reinforcement of Fuselage Skin on Right-Hand Side of Bulkhead 2	N/A
60	01/10/1966	Triple Seats	N/A
61	01/10/1966	Exhaust Stacks	N/A
62 Rev. B	01/05/1967	Flettner Tabs	N/A
63	01/10/1966	Chain Tensioner for Landing Flap Control	N/A
64	01/10/1966	Adjustment of Chain Tension of Horizontal Stabilizer Control	N/A

Ref. No.	Issue Date	Title	SB No.
65	01/09/1966	Rudder Pedal Support	N/A
66	01/10/1966	Attachment of Rudder Control Lever	N/A
67	01/10/1966	Elevator Attachment Bracket	N/A
68	01/10/1966	Fairleads on Pulley Support for Aileron Cables Behind Bulkhead 3	N/A
69	01/11/1967	Oil Drain Valve for UACL PT6A Engines	N/A
70	01/03/1967	RATIER FIGEAC Propeller FH 76 Modification No. 16	N/A
71	01/06/1967	Fastening of Tip Plates to Horizontal Stabilizer	N/A
72	01/06/1967	Trim Cable Guide Tubes on Bulkhead 8	N/A
73	01/06/1967	Sliding Door Installation	N/A
74	01/06/1967	Cable Pulley Layout on Bulkhead 2 and 11	N/A
75	01/11/1967	Leak Oil Separator	N/A
76	01/11/1967	Fixed Spoilers on the Wing	N/A
77	01/05/1968	Screen in Cabin Air Supply Duct	N/A
78	01/05/1968	Air Filter for Gyro Instruments	N/A
79	12/02/1968	Teleflex Reversing Linkage Terminals on PT6A-6 and BT6A-20 Engines	N/A
80	01/04/1968	Rudder Bottom Nose Rib	N/A
81 Rev. A	01/06/1968	Aileron Mass Balance Attachment Bolt	N/A
82	01/06/1968	Fuel Tank Filler Cap	N/A
83 Rev. A	01/02/1971	ASTAZOU Engine Mounting, Channel on Support Station 2	N/A
84	01/08/1968	Aileron and Landing Flap Support Bracket	N/A
85	01/07/1968	Power Lever Assembly	N/A
86 Rev. A	01/06/1969	Engine Cooling System on Lycoming powered PORTER	N/A
87 Rev. A	01/02/1971	PT6A Engine Installation FCU Bleeding System	N/A
88	01/12/1968	Hatch Door Locking Indicator	N/A
89 Rev. A	01/09/1969	Aileron Mass Balance Weight	N/A
90	01/03/1969	Electrical Priming Valve for Lycoming GSO-480 Engine	N/A
91	01/01/1969	Propeller Overspeed Hydraulic Governor	N/A
92	01/03/1969	Rudder Trim Cable Guard	N/A
93	01/06/1969	Corrosion of Wing Strut Attachment Bracket	N/A
94 Rev. B	01/12/1976	Compressor Wash Procedure on PT6A Turbine Engine	N/A
95	01/03/1971	Electrically Operated Landing Flaps	N/A
96 Rev. A	01/07/1971	Sliding Door - Modification of Roller Attachment and Travel Stops	N/A
97	01/02/1970	Tail Gear - Attachment Bracket	N/A

Ref. No.	Issue Date	Title	SB No.
98	01/02/1971	Additional Water Drain Holes	N/A
99	01/02/1970	Reinforcement Bracket - Corrosion	N/A
100	01/03/1970	Antireversing Switch on PT6A Engine	N/A
101	01/05/1970	Anti- Reverse System - Modification	N/A
102 Rev. A	01/04/1971	Horizontal Stabilizer - Front Bearings	N/A
103	01/06/1970	Elevator Control Cable - Support Guides at No.12 Bulkhead	N/A
104 Rev. A	01/11/1970	Dual Cylinder Brakes	N/A
105	01/05/1971	Wing Struts - Internal Corrosion	N/A
106	01/09/1970	Horizontal Stabilizer - Trim System	N/A
107	01/05/1971	Elevator Attachment Bracket	N/A
108 Rev. 1	01/11/1971	Elbow-Fittings on Fuel Supply Line on GSO-480 Engine Installation (Additional Information)	N/A
109 Rev. B	01/07/1980	Electrical Stabilizer Trim Actuator	N/A
110	01/07/1971	Fuel Pressure Gauge - Color Coding	N/A
111	01/02/1971	Brake Line Attachment Clamps on V-Struts	N/A
112	01/08/1971	Stowage Rack for Tail Wheel Steering Bar	N/A
113	01/08/1971	Replacement of Hinge Door Buffer	N/A
114	01/09/1971	Oil Cooler Drain	N/A
115	01/10/1971	Suspension of Oil Cooler and Exhaust Gas Collector/Heat Exchanger	N/A
116	01/12/1971	Floor Hatch Trap Door - Retracting Mechanism	N/A
117	01/12/1972	Suction Limitation for Gyro Instruments	N/A
118	01/12/1972	Inboard Fuel Tank Vent System	N/A
119	01/12/1972	Integral Fuel Tank - Increase to 2 x 85 US-Gal. Usable Capacity	N/A
120	01/01/1973	Rudder Bars in Cockpit	N/A
121	01/02/1976	Q-STOL Installation	N/A
122	01/12/1973	Battery Overtemperature Warning System	N/A
123	01/05/1974	Fuel Quantity Indicating System	N/A
124	01/01/1976	Landing Flap End Rib Reinforcement	N/A
125	01/03/1976	Electrical Landing Flap Control - Bellcrank Mounting Bolt Bearing	N/A
126	01/04/1976	Fuel Filter	N/A
127	01/04/1976	Horizontal Stabilizer Control - Cable Tensioner	N/A
128	01/08/1976	ASTAZOU Engine Control - Emergency Stop Control Cable	N/A
129	01/04/1977	Main Fuel Filter - 20 Micron Element	N/A
130	01/11/1976	Inspection of Aileron and Flap Actuating Rods	N/A

Ref. No.	Issue Date	Title	SB No.
131	01/04/1977	PT6A Engine Shock Mounts	N/A
132	01/07/1977	Fuel Cock	N/A
133	01/06/1979	Overspeed Governor on PT6A Engines - Change of Test Procedure	N/A
134	01/07/1979	Dual Control Brake Installation	N/A
135	01/02/1980	Fuel Return Line Check Valve - Relocation	N/A
136	01/09/1981	Replacement of Aileron Locks	N/A
137	01/12/1982	Aileron, Elevator and Rudder Gust Locks - Modification and Replacement	N/A
138 Rev. 3	01/09/1984	Replace Aileron/Flap Mount Attachment Fittings	N/A
139 Rev. 1	01/12/1984	Landing Flap Mounting Brackets - Inspection and Replacement	N/A
140 Rev. 1	15/02/1984	Flaps - Electrical Actuator Mounting Bracket - Inspect/Replace Bracket Support Structure	N/A
141 Rev. 2	01/12/1984	Landing Gear - Install Tail Wheel Guard (Para Version)	N/A
142	01/12/1984	Vertical Stabilizer - Replace Gusset Plates at Rudder Hinge Attachment Points	N/A
143	01/12/1984	Horizontal Stabilizer - Replace Gusset Plate at Elevator Hinge Attachment Points	N/A
144	01/12/1984	Horizontal Stabilizer - Install Standard Repair Plate	N/A
145	01/03/1987	Underwing Tank Fuel System - Pressure Switch Replacement	N/A
146	01/03/1987	Spark Ignition System for PT6A-27	N/A
147	01/05/1985	Electric Trim Actuator Attachment Bracket - Inspection and Modification	N/A
148 Rev. 3	09/01/2019	Stabilizer Electrical Actuator Trim System	N/A
149 Rev. 3	20/09/2018	Modification of H2 Aircraft to H4 Standard	N/A
150 Rev. 1	01/09/1988	Low Suction Warning Light	N/A
151	01/11/1987	Fuel Drain Collector Tank	N/A
152	01/12/1985	Flight Control Internal Lock - Removal of Complete Assembly	N/A
153	01/10/1986	Ski Fit. Installation - Removal Procedure	N/A
154	01/11/1987	Door Frame Strengthening	N/A
155	01/03/1987	Modification of Flight Control Internal Lock	N/A
157	01/03/1987	Reduction of Propeller RPM to Comply With Noise Regulations	N/A
158 Rev. 1	15/09/1994	Modification of Elevator Balance Tab Hinges	N/A
159	01/11/1987	Rudder Trim Tab Control Lever	N/A
160 Rev. 2	30/11/1995	Tail Landing Gear Shock Strut - Tail Oleo Strut H4	N/A
161	30/11/1989	Reduction of Propeller Speed	N/A
162	10/11/1989	Flight Controls - Rudder Pedal Supports - Fatigue Cracks	N/A

Ref. No.	Issue Date	Title	SB No.
163	15/12/1992	Landing Gear - Brackets - Modification of Brake Cylinders to Prevent Possible "Over-Centering" of Brake Mechanism	N/A
164	14/04/1994	Emergency Fuel Control System - Manual Override	N/A
165	07/02/1994	Inspection of Horizontal Stabilizer Hinge Brackets	N/A
166 Rev. 1	26/08/1997	Rear Fuselage - Reinforcement Between Bulkheads 12 and 13	N/A
167	12/04/1995	Installation of Lead-Acid Battery	N/A
168	06/06/1995	EPU Over-Voltage Protection Device	N/A
169 Rev. 1	25/06/1997	Improved Tail Wheel Assembly for H4 Configuration	N/A
170	16/10/1995	Modification of V-Struts	N/A
171	18/10/1995	Modification of the Collector Tank Venting System	N/A
172	30/11/1995	Modification of Tail Wheel Trailing Arm Cover Plate	N/A
174 Rev. 2	07/07/1999	Aileron/Flap Mounting Bracket Bolt Replacement	N/A
176	08/02/2001	Power Plant - Engine Drains Installation - Extension of the Oil Breather Pipe	N/A
177	10/01/2000	Fuel - Distribution - Reversion to Old Standard of Fuel Pipe Installation in the Fuselage	N/A
178	29/09/1999	Flight Controls - Horizontal Stabilizer - Inspection of the Actuator	N/A
179	15/05/2000	Fuel - Distribution - Verification of Fuel Return-Line Check-Valve Location	N/A
180 Rev. 3	13/10/2011	Flight Controls - Horizontal Stabilizer - Installation of a Trim Warning System	N/A
181	21/11/2001	Fuel - Distribution - Engine Driven Pump - Torque Check of Relief-Valve-Body Screws	28-001
182	20/12/2001	Flight Controls - Ailerons - Configuration of Mass Balance Weights and Flettner Tab	57-001
183	13/05/2002	Fuel - Distribution - Engine Driven Pump - Replacement of the Relief-Valve-Body Housing and Seals	28-003
184	05/06/2002	Flight Controls - Aileron Controls - Bellcrank Assemblies - Inspection and Replacement of Bearing Housings	27-001
185	27/11/2002	Wings - Outer Wing - Integral Fuel-Tank Rib Assemblies - Inspection and Repair	57-002
186	20/08/2004	Electrical Power - Remote-Control Circuit Breaker - Replacement	24-001
187	21/09/2004	Equipment and Furnishings - Emergency Equipment - Installation of Kannad 406AF ELT	25-001
188 Rev. 1	01/06/2005	Fuselage - Rear Fuselage - Stabilizer-Trim Attachment Components - Inspection	53-001
189 Rev. 1	18/07/2007	Wing - Wing Strut Fitting - Inspection for Corrosion and Replacement	57-003
190 Rev. 2	24/09/2007	Fuselage - Stop Nuts - Replacement	53-002

Ref. No.	Issue Date	Title	SB No.
191	08/08/2006	Landing Gear - Locking Plate Attachment Screw - Replacement	32-001
192	26/09/2006	Navigation - Mode S Transponder KT73 - Installation	34-001
193 Rev. 2	29/04/2008	Landing Gear - Wheels and Brakes - Brake Pedals - Freedom of Movement Check	32-002
194	16/04/2007	Wing - Wing Strut Fitting - Inspection for Cracks	57-004
195 Rev. 2	19/05/2008	Wing - Wing Strut Fitting - Inspection for Cracks	57-005
196	02/07/2008	Flight Controls - Flaps - Inspection of the Leaf Springs in the Flap Operating Mechanism for Cracks	27-002
197	02/07/2008	Flight Controls - Flaps - Replacement of the Leaf Springs in the Flap Operating Mechanism	27-003
198	15/12/2008	Fuel - General - Nitril Hose Embrittlement - Replace Hoses	28-004
199	13/11/2009	Fuel - Distribution - Change to the Wiring of the Time Delay Relays of the Underwing Fuel System	28-005
200	07/10/2010	Airworthiness Limitations - General - People's Republic of China (PRC) Certification of PC-6 / B2-H4 Aircraft (Available on Request)	04-001
201	07/12/2010	Lights - Exterior Lights - Navigation/Strobe Light Assemblies and Strobe Light Power-Supply Units - Replacement	33-001
202	04/05/2011	Airworthiness Limitations - General - Brazil Certification of PC-6 / B2-H4 Aircraft (Available on Request)	04-002
203	29/06/2011	Equipment and Furnishings - Passenger Seats - Installation of Seats with a Torso Restraint System	25-002
204	31/08/2011	Landing Gear - Wheels and Brakes - Replacement of the Master Brake Cylinder (P/N 119.50.06.055)	32-003
205 Rev. 1	25/11/2011	Stabilizer - Elevator and Rudder - Inspection of Hinge Bolt Locking	55-001
206 Rev. 4	21/09/2018	Landing Gear - V-Strut Assembly - Installation of Improved Stone Guards	32-004
207 Rev. 1	18/02/2016	Stabilizers - Horizontal Stabilizer - Inspection and Repair of the Horizontal Stabilizer to Fuselage Attachments	55-002
208 Rev. 3	06/11/2017	Stabilizers - Elevator and Rudder - Modification of the Hinge Bolt Installation	55-003
209 Rev. 1	18/06/2014	Airworthiness Limitations - General - IAC AR Certification of PC-6 / B2-H4 Aircraft (Available on Request)	04-003
210	08/01/2014	Power Plant - Engine Drains Installation - Installation of a Drain Tank for the Engine Drains	71-001
211	26/01/2015	Auto Flight - Autopilot - Temporary Placard Installation - PC-6/B2-H4 Aircraft Registered in the People's Republic of China (PRC) (Available on Request)	22-001
212	24/02/2016	Placards and Markings - Internal Placards - Installation of a Placard with Data for the Control-Column Grip-Assy Switches	11-001
213	26/02/2016	Propeller - Propeller Control - Installation of a Replacement Propeller Control Cable P/N 941.94.11.432	61-001

Ref. No.	Issue Date	Title	SB No.
214	13/05/2016	Wings - Ailerons - Inspection of the Aileron Mass-Balance Counterweight Attachment	57-006
215 Rev. 1	13/10/2016	Fuselage - Rear Fuselage - Stabilizer-Trim Attachment Components - Inspection	53-003
216	09/11/2016	Fire Protection - Fire Extinguisher Installation - Installation of a Replacement Fire Extinguisher P/N 959.08.06.220	26-001
217	26/06/2017	Lights - External Lights - Introduction of LED Landing Lights	33-002
218	22/12/2017	Lights - Exterior Lights - Introduction of LED Red Beacon-Lights	33-003
219 Rev. 2	07/11/2018	Doors - Door Assembly, Frame 6 - Replacement with Seat Cushion Stowage and New Control Stick Stowage on the Radio Rack	52-001
220 Rev. 2	06/02/2019	Flight Controls - Horizontal-Stabilizer Trim-System - Relocation of the Stab Trim Circuit-Breaker	27-004
221 Rev. 1	07/07/2018	Indicating/Recording Systems - Horizontal-Stabilizer Trim Warning-System - Installation of Adjustable Contact Plates	31-001
222 Rev. 1	04/09/2018	Flight Controls - Rudder - Rudder Shaft Assy - Inspection for Approved Rivet Configuration	27-006
223	02/07/2018	Flight Controls - Flaps - Flap Actuator - Pushrod Assy - Inspection for Incorrectly Installed Taper Pins and Possible Rework	27-005
224	02/07/2018	Stabilizers - Horizontal Stabilizer - Hinge Brackets - Fastener Inspection and Possible Rework	55-004