

**TEMPORARY REVISION NO. 12
TO PC-12/47E PILOT'S OPERATING HANDBOOK**

NORMAL PROCEDURES – PCL REVERSE THRUST LATCH LEVER

Record the incorporation of this Temporary Revision on the Log of Temporary Revisions, if required by Pilatus Service Bulletin 76-002.

SECTION 4 – NORMAL PROCEDURES

Paragraph 4.3.8 Cockpit, step 19 is changed as follows:

19. Power Control Lever

IDLE DETENT. Tighten PCL friction wheel as required. Pull reverse thrust latch handle up then release and check for free movement downwards. Confirm presence of PCL idle detent.

CAUTION

DO NOT OPERATE THE PCL FRICTION WHEEL IN FLIGHT.