

FOR PLANNING PURPOSES

SERVICE BULLETIN

SERVICE BULLETIN NO: 25-027

REF NO: 179

MODIFICATION NO: 030078

ATA CHAPTER: 25

EQUIPMENT AND FURNISHINGS - EMERGENCY EQUIPMENT EMERGENCY-LOCATOR-TRANSMITTER CONTROL PANEL - REPLACEMENT

1. Planning Information

A. Effectivity

PC-12 and PC-12/45 aircraft MSN 321 and MSN 401 thru MSN 500

PC-12 AND PC-12/45 aircraft Post SB 25-022.

B. Concurrent Requirements

None

C. Reason

As an option, operators can install a new smaller Emergency-Locator-Transmitter (ELT) remote control panel (RCP).

D. Description

This Service Bulletin (SB) gives the data and instructions necessary to remove the installed RCP and install a smaller RCP.

This SB supersedes SB 25-024.

Revision 1 to this Service Bulletin to change the P/N of the LH Pilots Crossbar Panel from 531.13.12.151 to 531.13.12.153.

E. Compliance

Optional.

F. Approval

The technical content of this document is approved under the authority of FOCA DOA No. FOCA.JA.002.

PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Manpower

	Total
Preparation	1
Removal of the installed RCP	0.5
Installation of the new RCP	2
Close up	1
TOTAL MAN-HOURS	4.5

H. Weight and Balance

(1) Weight Change

Not affected.

(2) Moment Change

Not affected.

I. Electrical Load Data

Not changed.

J. Software

Not changed.

K. References

Aircraft Maintenance Manual (AMM), 24-00-00, 25-10-01, 25-63-20 and 34-41-11.

L. Publications Affected

Pilots Operating Handbook, 7-133 and 134

AMM, 25-63-20

Illustrated Parts Catalog, 11-30-00 and 25-60-00.

M. Interchangeability of Parts

Pre and Post-Service Bulletin 25-027 ELT RCP are not interchangeable.

2. Material Information

A. Material - Price and Availability

Operators should send orders for SB Modification Kits, to their Authorized Pilatus Service Center, or to:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND

General Aviation:
Tel : + 41 41 619 6208
Fax: + 41 41 619 7311
eMail:
SupportPC12@pilatus-aircraft.com

Government:
Tel : + 41 41 619 6509
Fax. + 41 41 619 6224
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT
11755 AIRPORT WAY
BROOMFIELD, CO 80021.
UNITED STATES OF AMERICA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
PO BOX 732
MARLESTON SA 5033
AUSTRALIA

Tel : (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

Operators are requested to advise Pilatus Aircraft Ltd, of the Manufacturer's Serial Number (MSN) and the flying hours of aircraft which are affected by this SB.