

# SERVICE BULLETIN

SERVICE BULLETIN NO: 28-002

REF NO: 010

MODIFICATION NO:

ATA CHAPTER: 28

## INSTALLATION OF A NEW FUEL EMERGENCY SHUT-OFF LEVER

### 1. Planning Information

#### A. Effectivity

- (1) PC-12 aircraft MSN 101 and from MSN 103 up to and including MSN 160.
- (2) This Service Bulletin has been incorporated on MSN 102 and will be incorporated, prior to delivery, on aircraft MSN 161 and subsequent.

#### B. Reason

In order to prevent any mistake between operating the **FUEL** EMERG SHUT-OFF lever and the **ECS** EMERG SHUT-OFF, PILATUS has developed a locking device for the **FUEL** EMERG SHUT-OFF lever.

#### C. Description

Accomplishment of this Service Bulletin consists of completing the following tasks:

**NOTE:** Operators should be aware that the following task could be performed in conjunction with the mandatory SB 29-001 (Modification of the Hydraulic Hand-pump Handle).

- (1) Remove the old shut-off lever from the center console.
- (2) Installing a locking bracket.
- (3) Installing a new shut-off lever complete with locking catch and operating mechanism.

#### D. Compliance

Recommended.

#### E. Approval

The technical aspects of this Service Bulletin have been approved by the Federal Office for Civil Aviation (FOCA) of Switzerland.

**NOTE:** PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

**SERVICE BULLETIN**

**F. Manpower**

**FOR PLANNING PURPOSES**

<b>Task</b>	<b>Man-hours</b>
Preparation	1.00
Installation	0.50
Close-Up	1.00
<b>TOTAL MAN-HOURS</b>	<b>2.00</b>

**NOTE:** Man-hours figures are calculated for units installed in the aircraft and represent the total time estimated for the task.

**G. Material - Cost and Availability**

**(1) Material**

Operators should send orders, for Service Bulletin modification kit, to:

PILATUS AIRCRAFT LTD,  
MARKETING CUSTOMER LIAISON (MCLS)  
CH 6370 STANS, Tel No: +41 41-6196 233  
SWITZERLAND. Fax No: +41 41-6103 351

or contact your Authorized PILATUS PC-12 Service Center.

**NOTE:** Operators are requested to advise Pilatus Aircraft Ltd. of the Manufacturers Serial Number (MSN), the flying hours and landings of aircraft which are allocated for this Service Bulletin.

**(2) Cost and Availability**

**H. Tooling**

None.

**I. Weight and Balance**

Not Affected.

**J. References**

AMM, 29-00-00, Page Block 201, 25-10-01, Page Block 401  
IPC, 28-20-00, Fig. 02

**K. Publications Affected**

IPC, 28-20-00, Figure 02