

FOR PLANNING PURPOSES

SERVICE BULLETIN

SERVICE BULLETIN NO: 31-002

REF NO: 122

MODIFICATION NO: 990004

ATA CHAPTER: 31

INDICATING/RECORDING SYSTEMS INTRODUCTION OF A NEW GLARESHIELD

1. Planning Information

A. Effectivity

All PC-12 and PC-12/45 aircraft from MSN 101 up to and including MSN 260.

B. Concurrent Requirements

None

C. Reason

(1) Problem

The initially installed glareshield is no longer available.

(2) Cause

A new, better design of the glareshield is available to replace the original item.

(3) Solution

Install the new type of glareshield.

D. Description

This service bulletin gives the necessary data and instructions to replace the glareshield.

E. Compliance

Optional.

F. Approval

The technical aspects of this Service Bulletin have been approved by the Federal Office for Civil Aviation (FOCA) of Switzerland.

NOTE: PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Manpower

	Total
Preparation	4
Modification of the frame panel support	1
Close up	6
TOTAL MAN-HOURS	11

H. Weight and Balance

(1) Weight Change

Not affected.

(2) Moment Change

Not affected.

I. Electrical Load Data

Not changed.

J. Software

Not changed.

K. References

Aircraft Maintenance Manual (AMM), Chapter 24-00-00, 25-10-03 and 33-10-01.

L. Publications Affected

Illustrated Parts Catalog (IPC), Chapter 31-10-00.

M. Interchangeability of Parts

Pre and Post SB glareshields are not interchangeable without modification to the panel frames and the transfer of the sight line device.


SERVICE BULLETIN

FOR PLANNING PURPOSES

2. Material Information

A. Material - Price and Availability

Operators should send orders for Service Bulletin modification kits, to their Authorized Pilatus Service Center, or to:

PILATUS AIRCRAFT LTD.,
CUSTOMER LIAISON MANAGER,
CH 6371 STANS,
SWITZERLAND.

or PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : + 41 41 619 6319 (General aviation)

Tel : + 41 41 619 6509 (Government)

Fax: + 41 41 619 6224

Tel : 303 465 9099

Fax: 303 465 6040

NOTE: Operators are requested to advise Pilatus Aircraft Ltd, using the Service Bulletin Evaluation Sheet, of the Manufacturer's Serial Number (MSN) and the flying hours of aircraft which are allocated for this Service Bulletin.