



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

# SERVICE LETTER

**SUBJECT: AUTOPILOT**

To all Customers and Operators:

Date: Dec 22/04

This Service Letter is issued to draw attention to the following vendor information:

**1. Component Maintenance Manual - Document No. 02256**

A new Component Maintenance Manual (CMM) (Document No. 02256) is now available to Operators of PC-12 and PC-12/45 aircraft and should be used for the configuration of autopilot (AP) computers (Part No. 522.10.12.053).

**2. New Autopilot Configuration**

A new AP configuration (Part No. 522.10.12.055) which contains a modified option module that gives improved AP yaw damping performance is now available to Operators. PILATUS recommends Operators to up-date the AP computers (Part No. 522.10.12.053) in their aircraft to this latest standard. CMM 02256 should also be used to incorporate the new AP configuration (Part No. 522.10.12.055).

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,  
CUSTOMER SUPPORT MANAGER,  
CH-6371 STANS,  
SWITZERLAND.

General Aviation  
Tel : + 41 41 619 6208  
Fax: + 41 41 619 7311  
eMail: SupportPC12@pilatus-aircraft.com  
Government  
Tel: + 41 41 619 6509  
Fax: + 41 41 619 6224  
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,  
PRODUCT SUPPORT DEPARTMENT,  
11755 AIRPORT WAY,  
BROOMFIELD, CO 80021.  
USA

Tel : 303 465 9099  
Fax: 303 465 6040  
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,  
PO BOX 732,  
MARLESTON SA 5033,  
AUSTRALIA

Tel : (08) 8234 4433  
Fax: (08) 8234 4499  
Free Call: 1800 445 007  
eMail: info@pilatus.com.au

