

**TEMPORARY REVISION NO. 32
TO PC-12/47E PILOT'S OPERATING HANDBOOK
REPORT NO. 02277**

SECTION 3 – EMERGENCY PROCEDURES

ELECTRICAL POWER LOSS

This Temporary Revision adds a new procedure for electrical power loss and affects Section 3, page 3-44.

Record the incorporation of this Temporary Revision on the Log of Temporary Revisions.

SECTION 3 – EMERGENCY PROCEDURES

3.15 ELECTRICAL SYSTEM FAILURES

3.15.1 ELECTRICAL POWER LOSS

Indication – loss of electrical power.

- | | |
|---------------------------------|-----------------------------|
| 1. MASTER POWER switch | Check ON and guarded |
| 2. BATT and GEN switches | Check ON |

If indication remains:

- | | |
|--------------------|---------------------------------|
| 3. Aircraft | Land as soon as possible |
|--------------------|---------------------------------|

----- **END** -----

