

SUBJECT: EGPWS MK VI Terrain Database Update.

To all Customers, Operators and Service Centers:

Date: Nov 24/11

This Service Letter is issued to draw attention to the following information:

Terrain Database 461 and Envelope Modulation Database B07 for MK VI Enhanced Ground Proximity Warning System (EGPWS) Software Update.

Honeywell have made this software update available for users, and have issued the covering Service Information Letter D201104000062. The Honeywell SIL can be found at: www.pilatus-aircraft.com > Customer Support > Publications > PC-12 > Third Party Documents.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 3333
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
17 James Schofield Drive,
Adelaide Airport SA 5950,
AUSTRALIA

Tel : +61 (08) 8234 4433
Fax: +61 (08) 8234 4499
Free Call: 1800 445 007
eMail: SupportPC12@pilatus.com.au

INTENTIONALLY BLANK